1				Time stamp
1	987	313/49-51.ccls.	USPAT;	2004/06/12 15:17
_			US-PGPUB	
2	29	313/49-51.ccls. and (lamp (arc near3 tube)) and cap\$4 and	USPAT;	2004/06/12 15:24
	•	connect\$3 and (spring resilien\$3 damp\$3)	US-PGPUB	2004/06/42 45 27
3	0	313/317,318.\$2,49-51.ccls. and (lamp (arc near3 tube)) and	USPAT;	2004/06/12 15:27
		(socket cap\$4) and (contact\$ connect\$3) and (spring resilien\$3	US-PGPUB	
4	0	damp\$3) and (cas\$3 holder base housing) (313/317,318.\$2,49-51).ccls. and (lamp (arc near3 tube)) and	LICDAT	2004/06/12 15:27
7	U	(socket cap\$4) and (contact\$ connect\$3) and (spring resilien\$3	USPAT; US-PGPUB	2004/06/12 15:27
		damp\$3) and (cas\$3 holder base housing)	U3-FGFUB	
5	0	(313/317,318.\$2,49-51).ccls.	USPAT;	2004/06/12 15:26
	· ·	(313/317/310/42/13 31/.003.	US-PGPUB	200 1/00/12 15.20
6	205781	313/(317,318.\$2,49-51).ccls.	USPAT;	2004/06/12 15:26
			US-PGPUB	
7	205781	313/(317,49-51).ccls.	USPAT;	2004/06/12 15:26
			US-PGPUB	, , ,
8	1532	313/317,49-51.ccls.	USPAT;	2004/06/12 15:27
			US-PGPUB	
9	3051	313/317,49-51.ccls. 313/318.\$2.ccls.	USPAT;	2004/06/12 15:27
			US-PGPUB	
10	292	(313/317,49-51.ccls. 313/318.\$2.ccls.) and (lamp (arc near3	USPAT;	2004/06/12 15:34
		tube)) and (socket cap\$4) and (contact\$ connect\$3) and (spring	US-PGPUB	
11	23	resilien\$3 damp\$3) and (cas\$3 holder base housing)	LICDAT.	2004/06/12 15:24
11	23	(313/317,49-51.ccls. 313/318.\$2.ccls.) and (lamp (arc near3 tube)) and ((socket cap\$4) same (contact\$ connect\$3) same	USPAT; US-PGPUB	2004/06/12 15:34
		(spring resilien\$3 damp\$3) same (adapt\$3))	US-PGPUB	
12	40	(313/317,49-51.ccls. 313/318.\$2.ccls.) and (lamp (arc near3	USPAT;	2004/06/12 15:55
	.0	tube)) and ((socket cap\$4) same (spring resilien\$3 damp\$3) same	US-PGPUB	200 1/00/12 15.55
		(adapt\$3))	05.0.05	
13	225	439/\$.cc/s. and (lamp (arc near3 tube)) and ((socket cap\$4) same	USPAT;	2004/06/12 16:04
		(spring resilien\$3 damp\$3) same (adapt\$3))	US-PGPUB	
14	451	439/\$.ccls. and (lamp (arc near3 tube)) and (((socket cap\$4) with	USPAT;	2004/06/12 16:06
		(spring resilien\$3 damp\$3)) same (case casing housing base	US-PGPUB	
		carrier))		
15	0	439/775.ccls. and (lamp (arc near3 tube)) and (((socket cap\$4)	USPAT;	2004/06/12 16:05
		with (spring resilien\$3 damp\$3)) same (case casing housing base	US-PGPUB	
16	450	carrier)) 439/\$.ccls. and (lamp (arc near3 tube)) and (((socket cap\$4) with	USPAT;	2004/06/12 16:07
-0	430	((socket capsa) with (spring resilien\$3)) same (case casing housing base carrier))	US-PGPUB	2004/06/12 16:07
17	293		USPAT;	2004/06/12 16:08
	2,3	(spring resilien\$3) with (contact\$3 connect\$3)) same (case casing	US-PGPUB	200 1/00/12 10:00
		housing base carrier))	00 1 01 00	
18	66	439/\$.ccls. and (lamp (arc near3 tube)) and (((cap\$4) with (spring	USPAT;	2004/06/12 16:18
		resilien\$3) with (contact\$3 connect\$3)) same (case casing	US-PGPUB	, ,
		housing base carrier))		
19	5	439/239-244.ccls. and (lamp (arc near3 tube)) and (((cap\$4) with	USPAT;	2004/06/12 16:19
		(spring resilien\$3) with (contact\$3 connect\$3)))	US-PGPUB	
20	283	439/239-244.ccls. and (lamp (arc near3 tube))	USPAT;	2004/06/12 16:25
21			US-PGPUB	
24	127	439/619.ccls. and (lamp (arc near3 tube))	USPAT;	2004/06/12 16:25